



## Firestorm Cab Heater – Instruction Addendum

### **Heater Kit Modification:**

It has been determined that UniCoil is not necessary for this kit. As such, it has been removed for easier installation.

If you still wish to use UniCoil, you may purchase it separately at: [www.motoalliance.com](http://www.motoalliance.com)

### **Technical Support:**

- Customer Support Phone – 866-527-7637, press #1 at menu prompt
- Technical Support Phone – 866-527-7637, press #2 at menu prompt
- Email – [MotoInfo@motoalliance.com](mailto:MotoInfo@motoalliance.com)